
















NEXT PDH

Assembly Instruction - Návod k montáži

A		5	F	 M6*40	6	M		1
B		1	G	 M6*25	4			
C		1	H	 M8*25	3	N		1
D		1	I	 M5*15	2			
			J	 M6	1	O		1
E		2	K	 M8	1			
			L		1			

